


ROLLER SIDE COVERS FOR MUNCIE TRANSMISSIONS

We noticed that we sell more side cover oilseals for Muncies than synchronizer rings, and although the oilseals are inexpensive and easy to replace, this bothered us. When we investigated we discovered that the shifter shafts in many high-mile side covers are running in elongated bores, causing new oilseals to fail prematurely.



Obviously, a new side cover with round bores would solve the problem temporarily, but we wanted a permanent solution, so we made our shifters a true .750" (the OE shafts seem to be a few thou smaller) and supported them with needle bearings. It's standard on our new transmissions and available as a kit for your existing Muncie.

AGE

AUTO GEAR EQUIPMENT

530 STATE FAIR BOULEVARD
SYRACUSE, NEW YORK 13204

TEL: (315) 471-8141 • (800) 634-3001
FAX: (315) 471-8146 • (800) 537-4213

ROLLER SIDE COVERS FOR MUNCIE TRANSMISSIONS